

CCL was initially involved with this structure when it was damaged in storm force winds. We advised the emergency services on public safety as debris from the roof meant that the adjacent trunk road and surrounding areas had to be closed.

After the storm we subsequently assisted the owner in the design and remedial scheme for the building, producing drawings and detailed specifications to replace the roof covering.



If you require further information on how Canham Consulting Limited can help you on your project please contact us on 01603 430650 or alternatively email us at mail@canhamconsulting.co.uk